

Quoted for: CITY OF GALLUP
Customer Contact: JOHN WHEELER
Phone: / **Email:**

Quoted by: VICKIE BELL
Phone: / **Email:** vickie.bell@altec.com
Altec Account Manager: CHAD SPRAGUE

REFERENCE ALTEC MODEL

HD35A-22	22' Hydraulic Pressure Digger	\$337,805
----------	-------------------------------	-----------

(A.) SOURCEWELL OPTIONS ON CONTRACT (Unit)

1	HD35A-22-AWD	All Wheel Drive	\$24,211
2			
3			
4			

(A1.) SOURCEWELL OPTIONS ON CONTRACT (General)

1	PDR24	24" Diameter Auger for Pressure Digger	\$3,901
2	PDR36	36" Diameter Auger for Pressure Digger	\$4,235
3			
4			
5			
6			
7			
8			
SOURCEWELL OPTIONS TOTAL:			\$370,152

(B.) OPEN MARKET ITEMS (Customer Requested)

1	UNIT		
2	UNIT & HYDRAULIC ACC		
3	BODY		
4	BODY & CHASSIS ACC		
5	ELECTRICAL		
6	FINISHING		
7	CHASSIS		
8	OTHER		
OPEN MARKET OPTIONS TOTAL:			\$0

SUB-TOTAL FOR UNIT/BODY/CHASSIS: \$370,152
Delivery to Customer: \$1,882
TOTAL FOR UNIT/BODY/CHASSIS: \$372,034

(C.) ADDITIONAL ITEMS (items are not included in total above)

1			
2			
3			
4			

Pricing valid for 45 days

NOTES

PAINT COLOR: White to match chassis, unless otherwise specified

WARRANTY: Standard Altec Warranty for Aerials and Derricks - One (1) year parts warranty One (1) year labor warranty Ninety (90) days warranty for travel charges (Mobile Service) Limited Lifetime Structural Warranty. Chassis to include standard warranty, per the manufacturer.

TO ORDER: To order, please contact the Altec Account Manager listed above.

CHASSIS: Per Altec Commercial Standard

DELIVERY: No later than **30-45** days ARO depending on stock availability, FOB Customer Location

TERMS: Net 30 days

BEST VALUE: Altec boasts the following "Best Value" features: Altec ISO Grip Controls for Extra Protection, Only Lifetime Warranty on Structural Components in Industry, Largest Service Network in Industry (Domestic and Overseas), Altec SENTRY Web/CD Based Training, Dedicated/Direct Gov't Sales Manager, In-Service Training with Every Order.

TRADE-IN: Equipment trades must be received in operational condition (as initial inspection) and DOT compliant at the time of pick-up. Failure to comply with these requirements, may result in customer bill-back repairs.

BUILD LOCATION: St. Joseph, MO